

SSM 50073 - 2021 F150/Expedition/Navigator - 2.7L/3.5L Engines - Turbocharger Bypass Valve Replacement With Long Block Engine Replacement

When replacing the 6006 long block engine assembly in 2021 F150 vehicles equipped with a 2.7L or 3.5L EcoBoost or 3.5L PowerBoost with a vehicle build date on or after 19-July-2021 and 2021 Expedition/Navigator vehicles equipped with a 3.5L EcoBoost with a vehicle build date on or after 10-Feb-2021, the turbocharger bypass valve (9U465) and adapter (9V456) must also be replaced. For turbocharger bypass valve and adapter replacement procedures, refer to the Workshop Manual (WSM), Section 303-14.

APPLICABLE VEHICLES

2021 TRUCK: B8 U553N EXPEDITION
2021 TRUCK: B9 U554N NAVIGATOR
2021 TRUCK: FD P702N F150
2021 TRUCK: FD P702N F150
2021 TRUCK: FD P702N F150